Subject: Re: HASP service, NT4 SP4, and laptops
Posted by Bob Massey on Thu, 03 Dec 1998 08:00:00 GMT
View Forum Message <> Reply to Message

My printer won't work through the parallel port with the HASP installed,
on a Dell XPS R400 running NT 4.0 SP4.

Subject: Re: HASP service, NT4 SP4, and laptops
Posted by Peter Connell on Fri, 04 Dec 1998 08:00:00 GMT
View Forum Message <> Reply to Message

Forgive me for responding to myself, but some help from RSI indicates that
the HASP/floppy problem is related to Dell's approach to the external floppy
connection. If Dell were to switch to a USB connection, for example, the
problem goes away. I guess, but the HASP is supposed to be transparent to
the other hardware. Another way to solve the problem would be to drop the
HASP approach to licensing.

Peter Connell

Peter Connell wrote in message <744de7$m2n$1@lll-winken.llnl.gov>...
> In response to another posting from Mike Alport, I have installed IDL 5.2
on
> a PC running NT4 Workstation w/SP4, with HASP hardware node-locked license,
> and have not had problems.
>
> However, on a Dell Latitude laptop running Windows 98, the HASP seems to
> interfere with the parallel-port connected floppy drive, such that the
> floppy is not seen by the OS when the HASP is in place. Have others run
into
> this?
>
> Peter Connell
>
>
>