
Subject: Re: HASP service, NT4 SP4, and laptops
Posted by [Peter Connell](#) on Fri, 04 Dec 1998 08:00:00 GMT
[View Forum Message](#) <> [Reply to Message](#)

Forgive me for responding to myself, but some help from RSI indicates that the HASP/floppy problem is related to Dell's approach to the external floppy connection. If Dell were to switch to a USB connection, for example, the problem goes away. I guess, but the HASP is supposed to be transparent to the other hardware. Another way to solve the problem would be to drop the HASP approach to licensing.

Peter Connell

Peter Connell wrote in message <744de7\$m2n\$1@lll-winken.llnl.gov>...
> In response to another posting from Mike Alport, I have installed IDL 5.2
on
> a PC running NT4 Workstation w/SP4, with HASP hardware node-locked license,
> and have not had problems.
>
> However, on a Dell Latitude laptop running Windows 98, the HASP seems to
> interfere with the parallel-port connected floppy drive, such that the
> floppy is not seen by the OS when the HASP is in place. Have others run
into
> this?
>
> Peter Connell
>
>
>