Subject: Re: serial.dll for serial port under IDL Posted by theill on Fri, 24 Oct 2008 19:11:22 GMT

View Forum Message <> Reply to Message

## Thanks Rick!

I can now report success. The trick was, as Rick says, in the waiting - IDL is indeed reading the port too quickly after a write. This must be a problem for my particular device (a Meade ETX90 telescope that takes commands over the serial port). By testing the code below and inserting various waits it became clear that my device often wants to wait more than 0.05 seconds, and can wait as much as 1 second after sending a command to the port before reading the response.

Here is the working code:
start code insert
portstring='COM3' print,'Trying to open ',portstring n = comm_open(portstring, DATA=8,BAUD=9600, STOP=1, \$ PARITY='N', MODE=3);, BUFFERSIZE=8192) print,'handle from OPEN=',h
; WRITE data = bytarr(19) + byte(':Gt#') ; this command reads the telescope
; latitude from the Autostar (LX200 command set) b = comm_write(h, data) brint,'Result of write : ',b
wait, .15 data2 = bytarr(19) n=0 while (n eq 0) do begin b= comm_read(h, buffer=data2) print,'Result of read in loop : ',data2 x=where(data2 gt 0, n) endwhile print, 'Result of read once n was not 0: ',data2(0:n-1)
res=comm_close(/all) print,'result of comm_close command:',res end
end of insrted code

Example output of the above looks like this:

IDL> .GO

Trying to open COM3

BAUD=9600 DATA=8 PARITY=N STOP=1

handle from OPEN= 484

Result of write:

Result of read in loop: 43 53 53 223 52 49 58 48 48 35

0 0 0 0 0 0 0 0

Result of read once n was not 0: 43 53 53 223 52 49 58 48 48

35

result of comm\_close command: 1

----end example output

Thanks a lot for the help!

Peter Theill Denmark

On Oct 24, 6:10 pm, Rick Towler < rick.tow...@nomail.noaa.gov> wrote:

- > Peter sent some test code to me and I was able to reproduce the problem.
- It turns out that the issue is that IDL is "too fast" in that if you
- > write and then immediately read, IDL polls the serial port before
- > anything is in the serial port buffer. For small amounts of data this
- > means that you'll see nothing as Peter did. For large amounts of data
- > it means that you will not see all of the data. For example, sending
- > 4000 bytes of data and immediately reading results in (on my machine)
- > only 3984 bytes being returned. If you insert a pause between the write
- > and the read (wait, 0.1) you will Rx all 4000 bytes.

>

- > The issue is a bit more complicated than I have presented since you
- > never get those last few bytes even if you call comm read again. In my
- > case I should have 16 more bytes lying around but subsequent calls yield
- > nothing. So the guestion is, is this a result of a freak timing issue
- > that only comes up when you're looping back? Or is there a bug in the .dlm?

>

- > I'm leaning toward the prior but I don't know. I do know that if you
- > are providing you're own buffer to comm\_read it better be the same size
- or smaller than the serial port buffer or you get some weird results.

>

> Post your results Peter.

>

```
> -Rick
> ; test program for serial port reader
  ; NOTE: you MUST set the COM port number correctly first time or code
> crashes
> :
> portstring='COM3'
> print, 'Trying to open ', portstring
> handle=comm_open(portstring,DATA=8,BAUD=4800,STOP=1,PARITY=' N',mode=3)
> print, 'handle from OPEN=', handle
> :----- WRITE
> data=byte('6b')
> h=comm_write(handle,data)
> print,'Result of write: ',h
> ;----- READ
> buf = bytarr(5)
> h=comm_read(handle,BUFFER=buf)
> print,'Result of read: ',h
> print, 'Buffer read: ',buf
> ;------ CLOSE -----
> res=comm_close(/all)
> print, 'result of comm close command:', res
> end
>
>
> Rick Towler wrote:
>> peter.the...@gmail.com wrote:
>>> Hi, Thanks for your suggestions.
>>> On Oct 20, 8:19 pm, Rick Towler <rick.tow...@nomail.noaa.gov> wrote:
>>> Are you sure the serial dlm isn't working?
>>> No.
>>> Isolate the issue by doing a
>>> loopback test. Simply short pins 2 and 3 of the DB9 connector as
>>>> described here:
>>> http://zone.ni.com/devzone/cda/tut/p/id/3450
>>>> Then write a simple program in IDL that sends some data then reads it.
>>> Once you can send data to yourself then connect up the external devices
>>>> and try to communicate with them.
>>> Good idea! I am not much for soldering though - is the cable you
>>> describe a 'null-modem cable'? I have one of those.
```

```
>
>> No soldering required. You can use a paper clip:). That null modem
>> cable should have female connectors at both ends so you can plug one end
>> into your computer then short pins 2-3 at the other end of the cable.
>
>> Use Hyperterm to test your cable as described on that same webpage I
>> linked above. Once you know your cable is working then you can try IDL.
   The test in IDL will be as simple as this:
>> IDL> h=comm_open('COM1',BAUD=9600,DATA=8,MODE=3,PARITY='N',STOP=1)
>> IDL> b=comm_write(h,'This is a test')
>> IDL> data=comm_read(h)
>> IDL> print, data
   84 104 105 115 32 105 115 32 97 32 116 101 115 116
>> IDL> print, string(data)
>> This is a test
>> It looks as if the original .dll was built for IDL 5.6. I just
>> recompiled it for 6.4 for the test above. The issue might simply be
>> that you need to recompile. I know you're working with 6.3, but I'll
>> send you the .dll I just compiled and you can try that.
>
>> -Rick- Hide quoted text -
> - Show quoted text -
```