

---

Subject: Matrox Graphics Card Problems?

Posted by [davidf](#) on Wed, 20 Aug 1997 07:00:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Folks,

I've seen some more strange things this week with an IDL course I am teaching on Windows NT machines with Matrox graphics cards. The graphics in my IDL 5 object graphics programs are funny. For example, the axes labels routinely disappear on my surface plots when an expose event is generated. Or, occasionally, an image won't show up until a specific event is generated. I've even seen the view rectangle seem to "readjust" itself. :-)

I'm trying to collect more specific information. Has anyone else had problems? I NEVER see this kind of behavior with my Windows NT machine with a NeoMagic graphics card. Uh, I'm pretty sure it is NOT a programming error. :-)

I appreciate any and all information.

Cheers,

David

-----  
David Fanning, Ph.D.  
Fanning Software Consulting  
Customizable IDL Programming Courses  
Phone: 970-221-0438 E-Mail: [davidf@dfanning.com](mailto:davidf@dfanning.com)  
Coyote's Guide to IDL Programming: <http://www.dfanning.com>

---