
Subject: HP-GL Problem

Posted by [kueny](#) on Fri, 18 Feb 1994 15:19:31 GMT

[View Forum Message](#) <> [Reply to Message](#)

I have never been able to get the HP-GL driver for IDL to work with our system. We have an HP9000/700 running IDL 3.0.0 generating the HP-GL commands. We are trying to plot with an HP7550A plotter connected to an HP9000/300 via HP-IB. I have tried both xon_xoff settings. The plotter display keeps saying: '1: command not recognized'. The plot comes out, but several pen commands are dropped throughout the printout. The plotter works fine with several other software packages. Has anyone else seen this?

Thanks,

--

Kenneth L. Kueny | Glenn L. Martin Wind Tunnel | I kueny@eng.umd.edu
Project Engineer | University of Maryland | V (301) 405-6865,61,70
| College Park, MD 20742 | F (301) 314-9628
