
Subject: HASP service, NT4 SP4, and laptops
Posted by [Peter Connell](#) on Wed, 02 Dec 1998 08:00:00 GMT
[View Forum Message](#) <> [Reply to Message](#)

In response to another posting from Mike Alport, I have installed IDL 5.2 on a PC running NT4 Workstation w/SP4, with HASP hardware node-locked license, and have not had problems.

However, on a Dell Latitude laptop running Windows 98, the HASP seems to interfere with the parallel-port connected floppy drive, such that the floppy is not seen by the OS when the HASP is in place. Have others run into this?

Peter Connell
