Subject: Re: PV-WAVE & ZX card

Posted by mtasler on Mon, 18 Jul 1994 08:54:03 GMT

View Forum Message <> Reply to Message

I had some similar problems using PV-Wave widgets on an HP CRX24/Z. The animation speed before and after the installation of the CRX24/Z graphics board wasn't any different. The solution I found, was to set the keyword /pixmap, when calling the widgets. This caused a dramatic increase in animation speed. However for some mysterious reason, a black image appear in the cine-loop, which caused some flashing effect. :(

Martin Tasler