
Subject: Tektronix Terminals

Posted by [vvcns](#) on Thu, 11 Apr 1991 20:43:51 GMT

[View Forum Message](#) <> [Reply to Message](#)

Question:

Is anyone out there running PV-WAVE version 3.03 and having problems using shade_surf with Tektronix 4100 or Tektronix 4100 emulating terminals? I have contacted PVI about this and they seem to think there might be a bug with the driver but they are not really sure. I was just wondering if anyone else had this problem and if they had some type solution for it.

Thanks

Allen

Allen Holtz | vvcns@helios.lerc.nasa.gov
NASA Lewis Research Center |
21000 Brookpark Road |
Cleveland, Ohio 44135

It is fortune, not wisdom, that rules man's life.
